

# Performance Arts Center


Alarm Point

0331	1	Control Room
0332	2	Seating Area East/West
0334	1	105 J. S. Byrd Jr. Performance Room

## Administration

Alarm Point Quantity


Location	Count	Alarm Point	Quantity
West side of 101/102	1	0299	1
Stairwell Near Elevator	1	0325	1
Corridor opposite 201	1	0342	1
Corridor Near 207	1	0348	1
Stairwell Near 207	1	0357	1
Corridor Near 207	1	0361	1
Stairwell Near 207	1	0418	1
Corridor by 201	1	0549	1
Corridor Near 201	1	0556	1
Corridor Near 201	1	0557	1
Corridor Near 201	1	0566	1






0104	1	1	By 567	200	
0106	1		DB stairs between 2nd & 3rd Fl		
0595			DB stairs between 1st & 2nd Fl		
0596			DB stairs between 1st & 2nd Fl		
			By 112	110	
				0597	By 110
D-322				0598	By 110
05310					
014					

Cont	Quant	Location
0001	1	By 608
0095	1	By 608
0096	1	By 700A
0097	1	By 807C
0098	1	By 810 (100) B
0099	1	By 816
0326	1	By 601
333	1	By 611
334	1	By 600
0603	1	By 151







1307 | 1 | Stair #3 Between 2nd & 3rd Fl

By 339

1309 | 1 | Stair #2 Between 2nd & 3rd Fl

By 336

14 | 1 | Across From 325

1404 | 1 | 4th Floor By Elevator #

1406 | 1 | By 402

1410 | 1 | By 424


1411 | 1 | By 432

1425 | 1 | By 450

1513 | 1 | Stair #6 1st Floor

1514 | 1 | Stair #7 Between 2nd & 3rd Fl

1516 | 1 | Stair #7 Between 2nd & 3rd Fl





AP	Location	Comments
----	----------	----------

650501	1 IP: 60	T-7
0	1 In 118	Comments... 040



	0396	1 In 181
0207	VAU1	1100 55-10
	1100	55-10

0414 1 1 03/21/17

Female Locker 212

Manly Room 1st Floor

By 101

By 107

By 212

0419

0494

0495

0499

0559

# Academic Village

Alarm

Print Queue

Call

0754

0.5m Between Int. & Out.